

STATE OF CALIFORNIA
DEPARTMENT OF TRANSPORTATION

HC-5 (Rev. 5/93)

CONTRACT CHANGE ORDER NO. 143 SUPPL. NO. 0
ROAD 04-SF-80-13.2, 13.9 SHEET 2 OF 5 SHEETS
FEDERAL NO.(S) _____ CONTRACT NO.: 04-0120F4

Revise Special Provisions Section 10-1.59 "STEEL STRUCTURES," subsection "Shop Welding," subsection "Design Details," item G.2 as follows:

G. Dimensional Tolerances

2. Where a discontinuous member provides a continuous load path on either side of a through member, the method of marking and ensuring alignment shall be described in the dimensional control procedure. Misalignment between discontinuous members shall not exceed 10% of the thickness of the thinner member or 3 mm, whichever is less, except as noted otherwise on the plans.

